Flextur™
A more excellent way to work.

Cobot Welding Systems

Maximize Efficiency

Flextur's Quick-Change Welding Tables

72" x 36" Quick-Change Table



Flextur™ 72" x 36" Quick-Change Fixture Table for use with Flextur Cobot Docking Station and 72" x 36" Flextur Quick-Change Fixture Plate for faster change over and accurate fixture placement. As a part of the Cobot Welding System by Flextur™ this Quick-Change Table assists in creating an extremely accurate, efficient, safe, and highly productive cobot welding solution.

- Accurate within +/-.01"
- Leveling Feet
- 2-Hand safety switch
- Pneumatic operation
- Pneumatic quick connect included
- Grounding lugs & cable included
- Gridlok Innovation
- Patented Design





Part Number: **71500063**

Requires Docking Station (sold separately)

The Flextur Cobot Welding System solves these three major issues:

1. **Complexity in Automation:** Designed for simplicity, it ensures ease of use and repeatability.
2. **Transitioning from Hand Welding:** Streamlines the shift to automation, making it seamless for your team.
3. **Slow Changeovers:** Enables faster setups to mazimize arc-on time and boost productivity.





Flextur's advanced Cobot Welding System is equipped with Quick-Change Fixture Plates and has proven to boost productivity by over 300%!

When working with Flextur, you too can experience a surge in your metal manufacturing output, address labor and skills gaps, and overcome fixturing challenges.

The Modular Design of the Flextur Cobot Welding System adapts with you.

16875 Jericho Rd • Dalton, OH 44618
connect@**Flextur**.com • www.**Flextur**.com • 877-435-3988
111324 • COPYRIGHT FLEXTUR 2024

USA MADE